

BENDIX-SCINTILLA MAGNETOS

BENDIX BREAKER ASSEMBLIES

Early S4, S6 Mags

P/N 07-06305 (10-357173) with spring
(current production) **\$36.85 Ea.**
P/N 07-06306 (10-357174) without spring
(current production) **\$37.55 Ea.**

All above breaker assemblies used on either Right or Left Magnetos.
Late S4/S6 Mags, S200 Mags*

P/N 10-382584 (LH) **\$41.85 Ea.**
P/N 10-382585 (RH) **\$37.50 Ea.**

Used on many late Lyc. engines.

Note: Specify Bendix mag P/N e.g., 10-51369-29

REPLACEMENT COIL FOR BENDIX S4, S6 Mags

Airborne FAA-PMA approved coil replaces both Bendix 10-357164 & 10-357165. Retrofits virtually the complete range of Bendix S20 & S200 series mags. Furnished with long & short "coil to points" leads.

P/N ES-652 **\$108.95**

NOTE: Part Nos. 10-357164-1, 10-357165-1, 07-06303, 07-06304 are all equivalents for ES-652

REPLACEMENT COIL FOR BENDIX 1200 SERIES Mags

Aero Accessories, Inc. FAA-PMA approved coil is a direct replacement for Bendix 10-391088 coil as used on Bendix 1200 series mags at tremendous savings.

P/N 07-05600 **\$154.95**

REPLACEMENT COILS FOR CONTINENTAL ENGINES PER SERVICE BULLETIN NO. 637

TCM Ignition Systems has issued Service Bulletin No. 637 to retire from service certain older coils and rotating magnetos. The Bulletin applies to many S-20, S-200, S-600, and S-1200 series magnetos as identified in this chart. Compliance with this Bulletin is required at the next 100 inspection, annual inspection, or progressive maintenance inspection, whichever comes first. Order by new coil part number.

Magneto Series	Old Coil P/N	Color	New Coil P/N	Color	Our Price
S-20	10-51303	Opaque amber to Dark Purple	10-357164	Bright Red to Dark Red	\$166.75
	10-76384				
	10-160886				
S-20	10-163172	Opaque Amber to Dark Purple	10-357165-1	Bright Red to Dark Red	\$157.75
	10-163209				
S-200	10-160887				
S-1200	10-349271	Opaque Amber	10-391088-1	Blue to Olive Green to Black	\$207.95

ALTERNATOR FILTER

Replacement part for existing alternator filters. Wire won't break at the case and its clamp is made from heavy gauge steel. Double the capacitance compared to OEM alternator filters. For stubborn alternator noise, this Alternator filter combined with the Eliminator (P/N 11-08055) can trap a wide frequency range of electronic noise. Both of these filters have been thoroughly tested under a DO 160D and are FAA/PMA approved. P/N 11-08060 **\$59.95**



MAGNETO FILTER

Eliminates ignition noise. Install in primary lead of magneto. Not FAA approved. P/N 07-03200 **\$66.75 ea**



MAGNETO FILTER FAA APPROVED

Attenuates both low and high frequencies of noise generated from bendix magneto ignition systems. This filter has been used by avionics shops, OEM aircraft manufacturers, and FBO's, to attenuate and suppress pulsating noise generated by their aircraft's magneto systems. The magneto filter is FAA-PMA approved and is compatible with the bendix series S20, S21, S200, D3000, D4000 magneto. 1000 VDC working voltage, 5000VDC break down voltage. Capacitance: .05 uf-self healing technology. Heavy duty mounting clamp. Temp. range: -35°C to +80°C. Max. current: 20 amps P/N 07-00713 **\$68.80**



BENDIX MAGNETO GREASE

#10-27165 - Factory recommended lubricant for bearings in Bendix magnetos. 1 Lb. Can P/N 10-27165 **\$71.75**
#10-391200 - For use on distributor block bushing. Provides proper shaft lubrication.
8 oz. can P/N 10-391200 .. **\$68.75**
1 oz. tube P/N 07-02500 **\$3.95**



GROMMET STRETCHER

Stop Cutting Grommets!


- Stretch grommets over large plugs and fittings.
- Great for spark plug wires or molex plugs.

P/N 11-06946 **\$24.75**



BOGERT AVIATION P-LEADS

P-leads for all aircraft using a Slick or Bendix Style Magnetos. This includes nearly all piston aircraft such as: Cessna, Piper, Grumman, Mooney, as well as many homebuilt and experimental aircraft. As a general rule cables should be replaced when ever wear is apparent. Broken ground leads should not be permitted. A drop in rpm is expected when one magneto of the two mags is shut off. Should the propeller be moved by hand and a functional "hot" magneto exists, the engine may fire causing injury. If there is no drop in rpm the owner should call a mechanic immediately. Bogert is using 14gauge MS27500 wire with aviation approved terminals. The shrink tube has an adhesive inside the sleeve to improve durability and reduce the possibility of corrosion. Cables are ready to install.




Length inches	Slick Style		Bendix Round Nut		Bendix Hex Nut	
	Part No.	Price	Part No.	Price	Part No.	Price
30	11-06889	\$31.60	11-06891	\$69.25	11-06914	\$79.85
36	11-06870	\$32.95	11-06892	\$72.75	11-06915	\$88.75
42	11-06871	\$34.70	11-06893	\$73.75	11-06916	\$89.75
48	11-06872	\$35.50	11-06894	\$74.75	11-06917	\$88.50
54	11-06873	\$36.50	11-06895	\$75.75	11-06918	\$93.75
60	11-06874	\$37.50	11-06896	\$76.75	11-06919	\$92.25
66	11-06875	\$38.80	11-06897	\$78.75	11-06920	\$94.90
7	11-06876	\$39.85	11-06898	\$79.75	11-06921	\$95.00
84	11-06877	\$42.85	11-06899	\$82.75	11-06922	\$99.75
96	11-06878	\$46.50	11-06901	\$85.95	11-06923	\$103.75
108	11-06879	\$49.65	11-06902	\$89.80	11-06924	\$107.75
120	11-06880	\$53.75	11-06903	\$92.75	11-06925	\$110.75
132	11-06881	\$57.75	11-06904	\$99.75	11-06926	\$114.80
144	11-06882	\$60.75	11-06905	\$99.75	11-06927	\$117.75
156	11-06883	\$64.75	11-06906	\$103.75	11-06928	\$122.75
168	11-06884	\$67.75	11-06907	\$107.80	11-06929	\$124.75
180	11-06885	\$71.75	11-06908	\$110.75	11-06930	\$128.75
192	11-06886	\$74.90	11-06909	\$114.75	11-06931	\$131.80
204	11-06887	\$77.85	11-06910	\$116.99	11-06932	\$135.75
216	11-06888	\$81.90	11-06911	\$121.75	11-06933	\$138.75
228	11-06889	\$84.90	11-06912	\$124.75	11-06934	\$142.75
240	11-06890	\$88.75	11-06913	\$128.75	11-06935	\$145.75



GROUND TERMINAL KITS

For S-20 series mags. Kit No. 10-52306 (AN3105) **\$38.85**

Reg. No.	Part No.	No. Req.	Description
1	10-30299	1	NUT - Coupling (Ground Terminal)
2	10-56507	1	CROMMET Assy.(Ground Terminal)
3	10-3383	1	FERRULE - Inner (Ground Wire)
4	10-25725	1	SLEEVE - Insulating (Ground Wire)



For 20 series mags. Kit No. P/N 10-52305 . **\$85.95**

Reg. No.	Part No.	No. Req.	Description
1	10-37669	1	NUT - Coupling (Ground Terminal)
2	10-7030	1	FERRULE - Outer (Ground Wire)
3	10-7029	1	FERRULE - Inner (Ground Wire)
4	10-37668	1	SLEEVE - Insulating (Ground Wire)
5	2-155	1	WASHER - Ground Wire Contact

TCM/BENDIX IMPULSE COUPLINGS

Part No.	Price
10-40307	\$429.00
10-40309	\$496.00
10-40310	\$306.50
10-400313	\$421.00
10-40314	\$339.75
10-40315	\$339.75
10-40322	\$279.95
10-40325	\$365.95

\$70.00 core charge applies

TCM/BENDIX CAM ASSEMBLIES

Part No.	Price
10-40166-4	\$246.95
10-40166-6	\$252.95
10-40167-4	\$293.95
10-40167-6	\$249.95
10-40167-10	\$282.95

\$40.00 core charge applies